

Miconfiguration Report

Somerset College of Arts and Technology

Wellington Road

Taunton TA1 5AX

ProCurve Manager

Created by Network Consistency Module

CATEGORY	ITEMS	MISCONFIGURATION	REQ. ACTION
Port	10.100.1.1[GigabitEthernet2/5], 10.100.1.25[Trk7]	The link Port 10.100.1.1[GigabitEthernet2/5] speed is 1000000000 and port 10.100.1.25[Trk7] speed is 2000000000.	Ports speed should be same on both sides of link
Port	10.100.1.1[GigabitEthernet3/2], 10.100.1.11[Trk1]	The link Port 10.100.1.1[GigabitEthernet3/2] speed is 1000000000 and port 10.100.1.11[Trk1] speed is 2000000000.	Ports speed should be same on both sides of link
Port	10.100.1.3[GigabitEthernet3/1], 10.100.1.10[Trk1]	The link Port 10.100.1.3[GigabitEthernet3/1] speed is 1000000000 and port 10.100.1.10[Trk1] speed is 2000000000.	Ports speed should be same on both sides of link
Port	10.100.1.3[GigabitEthernet3/4], 10.100.1.12[Trk2]	The link Port 10.100.1.3[GigabitEthernet3/4] speed is 1000000000 and port 10.100.1.12[Trk2] speed is 2000000000.	Ports speed should be same on both sides of link
VLANS	10.100.1.1[GigabitEthernet1/7], 10.100.1.23[A1], VLANID:1	Port tag-type mismatch in devices 10.100.1.1,10.100.1.23 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.1[GigabitEthernet3/2], 10.100.1.11[Trk1], VLANID:1	Port tag-type mismatch in devices 10.100.1.1,10.100.1.11 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.1[GigabitEthernet3/16], 10.100.1.7[25], VLANID:1	Port tag-type mismatch in devices 10.100.1.1,10.100.1.7 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.

27 Oct 2005

Administrator

CATEGORY	ITEMS	MISCONFIGURATION	REQ. ACTION
VLANS	10.100.1.3[GigabitEthernet3/15], 10.100.1.40[25], VLANID:1	Port tag-type mismatch in devices 10.100.1.3,10.100.1.40 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[B3], 10.100.1.27[A1], VLANID:1	Port tag-type mismatch in devices 10.100.1.25,10.100.1.27 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[B4], 10.100.1.31[25], VLANID:1	Port tag-type mismatch in devices 10.100.1.25,10.100.1.31 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[C1], 10.100.1.32[26], VLANID:1	Port tag-type mismatch in devices 10.100.1.25,10.100.1.32 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[C2], 10.100.1.28[25], VLANID:1	Port tag-type mismatch in devices 10.100.1.25,10.100.1.28 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[C3], 10.100.1.29[25], VLANID:1	Port tag-type mismatch in devices 10.100.1.25,10.100.1.29 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.25[D1], VLANID:1, 10.100.1.34[25]	Port tag-type mismatch in devices 10.100.1.25,10.100.1.34 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.30[25], 10.100.1.29[26], VLANID:1	Port tag-type mismatch in devices 10.100.1.30,10.100.1.29 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.
VLANS	10.100.1.21[26], VLANID:1, 10.100.1.22[26]	Port tag-type mismatch in devices 10.100.1.21,10.100.1.22 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.

27 Oct 2005

Administrator

CATEGORY	ITEMS	MISCONFIGURATION	REQ. ACTION
VLANS	10.100.20.4[A3], VLANID:1, 10.100.20.9[25]	Port tag-type mismatch in devices 10.100.20.4,10.100.20.9 .	A VLAN assigned to a port connecting two 802.1Q-compliant devices must be configured with the same tag-type on both sides.