hp StorageWorks library and tape tools

File   View   Function   Options   Utilities   Help

Identity   Firmware   Test   Support   Frontpanel   Dev Perf   Sys Perf   Help

Scan | By Product | By Connection | Instructions

Libraries/Autoloaders
  HP C7145 (Address: 2/0.0.0)
Processo
Drives
  BNC
Other De

hp L&TT

The diagnostic functions are operating in restricted mode. Some functions may be disabled or limited while operating in restricted mode.

The restricted mode is entered if either the Product ID is not properly recognized, or if the device operates in 'boot code' and requires a firmware update.

OK

hp StorageWorks library and tape tools

File   View   Function   Options   Utilities   Help

hp L&TT - Pending I/O Request

Waiting for pending I/O request to complete...

Pending command:	3B (Write Buffer)
Already pending for:	345
Maximum:	600

This is not unusual for some commands, and is informational to show that the application is still responsive. To disable this feature, see the Preferences Dialog.

This dialog will update and close automatically 5 seconds after the I/O completes.

[Close]

...ware Files | Firmware Update Results |

	Current Rev	New Rev	Status
	2530	2260	Picker (1 of 3)

☑ Force Sequential Updates

File Selection:

Library Firmware File: C7145-8000, Rev: 2260, 03/06/2001 ▼   [Options...]

Drive Firmware File: Ultrium 1-SCSI, Rev: E36R/OEM2, 01/09/20 ▼

Firmware File Folder: C:\Program Files\HP StorageWorks Library and Tape Tools   [Browse]

Time Remaining: 16 min, 36 sec

[Update In Progress]

have the necessary firmware files stored locally, click the **Local Firmware Files** tab to download firmware from the HP website.

When you are ready to begin the firmware upgrade, click **Start Update**.