

HPUX 11i Supported Systems

Bezel or Model	32-bit Support	64-bit Support	Comments
A-Class: A180, A180C	Yes		PA-7300LC
A-Class: A400, A500		Yes	PA-8500 and newer processors
bp2200 blade (in an HP bh3710 chassis)		Yes	PA-8600 processor only; HP-UX model string: 900/800/HPServerBlade8600/3xx2
D-Class: D270/370, D280/380, D390	Yes	Yes	PA-8xxx (See D-Class Support for 11i 64-bit for firmware revision information.)
D-Class: All other	Yes		PA-7xxx
K-Class: Kx50, Kx60, Kx70, Kx80	Yes	Yes	PA-8xxx
K-Class: Kx00, Kx10, Kx20	Yes		PA-7xxx
L-Class: L1000, L2000, L3000		Yes	PA-8500 and newer processors
L-Class: L1500, L3000		Yes	PA-8700 and newer processors
N-Class: N4000		Yes	PA-8500 and newer processors
R-Class: R380, R390	Yes	Yes	PA-8000 and newer processors
rp2400		Yes	PA-8500 processor; HP-UX model string: A400-44 ¹
rp2430		Yes	PA-8700 processor; HP-UX model string: A400-6X
rp2450		Yes	PA-8500 and newer processors; HP-UX model string: A500-44 or A500-5X
rp2470		Yes	PA-8700 processors; HP-UX model string: A500-6X or A500-7X
rp5400		Yes	PA-8500 and PA-8600 processors; HP-UX model string: L1000-36, -44, -5X
rp5405		Yes	PA-8700 processors; HP-UX model string: L3000-6X

rp5430		Yes	PA-8700 processors; HP-UX model string: L1500-5X, -6X, -7X, or -8X
rp5450		Yes	PA-8500 and PA-8600 processors; HP-UX model string: L2000-36, -44, -5X
rp5470		Yes	PA-8700 processors; HP-UX model string: L3000-5X, -6X, -7X, or -8X
rp7400		Yes	PA-8700 processors; HP-UX model string: N4000-65 or N4000-75
rp7405 and rp7410		Yes	HP-UX model string: 9000/800/rp7410 (both rp7405 and rp7410) (See nPartition (Hard Partition) Systems.)
rp8400		Yes	PA-8700 and newer processors; HP-UX model string: S16K-A (See nPartition (Hard Partition) Systems.)
Superdome systems: Superdome 16-way, Superdome 32-way, Superdome 64-way		Yes	(See nPartition (Hard Partition) Systems.)
T-Class: T5xx	Yes		PA-7xxx
T-Class: T6xx	Yes	Yes	PA-8xxx
V-Class: V22xx, V2500, V2600		Yes	PA-8200 and newer processors

The following D-Class systems support HP-UX 11i 64-bit operation:

Table 2 D-Class Support for 11i 64-bit				
Model	CPU	Speed (MHz)	32/64 bit	Minimum Firmware Revision
D270/370	PA8000	160	Both	38.27 or later
D280/380	PA8000	180	Both	38.27 or later
D390	PA8200	240	Both	38.28 or later