

## 2- Current configuration information (drivers, firmwares, tools versions)

To check the compatibility of the new EVA firmware and the (HBAs, SAN/GbE2c switches), the following information are needed in the upgrade tasks:

### 1. Firmware

Component	Firmware version	Remarks
EVA 4000 Controller	5.10	
HBA (Fiber controller in the BL Server)	1.43	
Existing Brocade 4GB SAN Switch	5.0.16 (kernel: 2.4.19)	
New Brocade c-class SAN Switch AE372A (4/24 SAN SW)	????	
Blade enclosure switch (GbE2c)	Rev. 0A, Soft rev 2.2.0 (flash image)	
Existing 146GB FC disk	HP03 (BD1465822C)	HP05 is available
New 146GB FC Disk	HP05 (or HPD5)	Latest
Existing 500GB FATA Disk	HP03 (NB50058855)	No disk upgrade reqd.
New 1GB FATA disk	HP06	Latest

### 2. Driver version (using Windows Device Manager)

Name	Version
HBA (FC Card), Storport driver	9.1.0.13, 9.1.3.16
MPIO (Multipath IO)	1.16.3790.1609