



[Home](#)

[Settings](#)

[Tasks](#)

[Logs](#)

Environment

System

Thermal Degraded Action:

- Continue
 Shut Down

Overall Thermal and Fan Status: OK

Temperature Sensors

Sensor	Location	Temperature	Threshold	Type
<input checked="" type="checkbox"/> 1	CPU	25 C	54 C	Caution
<input checked="" type="checkbox"/> 2	CPU	40 C	68 C	Caution
<input checked="" type="checkbox"/> 3	IO Board	24 C	56 C	Caution
<input checked="" type="checkbox"/> 4	CPU	45 C	68 C	Caution

Fault Tolerant Fans

Fan	Location	Type	Present	Hot Pluggable	Speed	Redundant
<input checked="" type="checkbox"/> 1	CPU	Spin Detect	Present	Not Hot Plug	Normal	Not Redundant
<input checked="" type="checkbox"/> 2	IO Board	Spin Detect	Present	Not Hot Plug	Normal	Not Redundant