

HP ProLiant Firmware Maintenance CD 8.20 Release Notes



Part Number 502508-001
August 2008 (First Edition)

© Copyright 2008 Hewlett-Packard Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Microsoft, Windows, and Windows Server are U.S. registered trademarks of Microsoft Corporation.

Intended audience

This document is for the person who installs, administers, and troubleshoots servers and storage systems. HP assumes you are qualified in the servicing of computer equipment and trained in recognizing hazards in products with hazardous energy levels.

Contents

- Overview 4
- Firmware Maintenance CD 5
- HP Smart Update Manager 15
 - General topics 15
 - Command line 16
 - HP Smart Update Manager and component-related topics 16
- HP Firmware CD Browser Utility 18

Overview

These release notes discuss any issues and their potential workarounds, as well as special information regarding the contents of the Firmware Maintenance CD. For the latest information and any updated release notes, see the SmartStart website (<http://www.hp.com/servers/smartstart>).

Firmware Maintenance CD

The Firmware Maintenance CD delivers a collection of firmware for HP ProLiant Servers and options. The Firmware Maintenance CD ISO image contents can be moved to a bootable USB Key using the HP USB Key Utility for Windows found on the HP website (<http://www.hp.com/go/support>). For additional information, see the HP Firmware Maintenance CD on USB Key `readme` file, which can be found on the Firmware Maintenance CD at `\usb\readme_fw820.txt`.

- To flash firmware using iLO virtual media, you must go into the settings and enable the high performance mouse support to sync up the mouse pointers between the local and remote servers. Upon completion, the mouse pointers track together and enable the user to click the Continue button. Because the Firmware Maintenance CD uses the high performance mouse driver, you must enable the corresponding entry in the Remote Console Settings (via the web page on the machine running the browser).
- Red Hat Enterprise Linux 5 automounts the CD with the `noexec` property set. To run Autorun, the CD must be unmounted, and then, manually remounted.
- The Firmware Maintenance CD (versions 7.91, 8.00, 8.10, and 8.10) cannot update firmware on SATA hard drives in an MSA1500cs or in MSA20s attached to an MSA1500cs that are attached to a ProLiant server through an Emulex Fibre Channel HBA.
- SCSI hard drive firmware can be updated in the following MSA1000 or MSA1500cs configurations using the Firmware Maintenance CD v7.90 or later:
 - Firmware for SCSI hard drives in an MSA1000 or MSA1500cs configuration that are attached to a ProLiant server via the following Fibre Channel HBA can be updated using the Firmware Maintenance CD v7.90 or later. Prior to Firmware Maintenance CD v7.90, you had to use Firmware Maintenance CD v7.40B to update the SCSI hard drive firmware in an MSA1000 or MSA1500cs configuration using this HBA.

HP model	Description	Vendor model name
FCA2101	Single Channel, 2 Gb, PCI-X	Emulex LP952L

- SCSI hard drive firmware can not be updated in the following MSA1000 or MSA1500cs configurations using the Firmware Maintenance CD v7.61 or later:
 - Firmware for SCSI hard drives in an MSA1000 or MSA1500cs configuration that are attached to a ProLiant server via the following Fibre Channel HBA can not be updated using the Firmware Maintenance CD v7.61 or later. You must use the Firmware Maintenance CD v7.40B to update the SCSI hard drive firmware in an MSA1000 or MSA1500cs configuration using this HBA.

HP model	Description	Vendor model name
DS-KGPSA-CB	Dual Channel, 1 Gb, PCI	Emulex LP8000

- Firmware for SCSI hard drives in an MSA1000 or MSA1500cs configuration that are attached to a ProLiant server via the following Fibre Channel HBAs can not be updated using the Firmware Maintenance CD v7.61 or later or the Firmware Maintenance CD v7.40B.

HP model	Description	Vendor model name
FCA2354	Single Channel, 2 Gb, PCI-X	Emulex LP9002L-F2

HP model	Description	Vendor model name
FCA2355	Dual Channel, 2 Gb, PCI-X	Emulex LP9002DC

- Firmware version 8.10 was the last release that contains the following. This firmware is baselined on the Firmware Maintenance CD 8.10, and it is still available for download on the HP website (<http://www.hp.com>).

Platform	Description	Version
—	SA 5300 Component	—
—	HP SATA HBA w/ RAID	—
—	HP ProLiant BL p-Class	—
—	All ROMPaq Components	—
—	ROM Flash Component - BF01885A34	—
—	ROM Flash Component - BF03685A35 drives	—
—	ROM Flash Component - BF07285A36 drives	—
—	ROM Flash Component - BF03664664 drives	—
—	ROM Flash Component - BF018863B8, BF036863B9, and BF072863BA drives	—
—	ROM Flash Component - BF00988282, BF01888283, BF03688284, BF03698287 drives	—
—	ROM Flash Component - BD00478273, BD0046826A, BD00978274 drives	—
—	ROM Flash Component - BD03698276, BD03688272, BD0729827A, BD07288277 drives	—
ML530 G2	ROM Flash Component for Windows® - HP ProLiant ML530 G2 Server	v2004.09.15
ML530 G2	ROM Flash Component for NetWare - HP ProLiant ML530 G2 Server	v2004.05.01
ML530 G2	ROM Flash Component for Linux - HP ProLiant ML530 G2 Server	v2004.09.15
DL320 G3	ROM Flash Component for Windows - HP ProLiant DL320 G3 Server	v2007.07.16
DL320 G3	ROM Flash Component for Linux - HP ProLiant DL320 G3 Server	v2007.07.16
DL320 G3	ROMPaq Firmware Upgrade for HP ProLiant DL320 G3 Server	v2007.07.16 (A)

- Firmware version 8.00 was the last release that contains the following Server ROM Flash components. They will continue to be available on the HP website (<http://www.hp.com>) for download.

Platform	Description	Version
—	MSA60 and MSA70 (Future firmware CD releases will include newer versions/releases of MSA 60/70 firmware)	1.42b
—	Dual CH Storage Controller – Windows	5.05.11 (A)
—	Ultra 3 Dual Channel HBA BIOS (Controller Firmware) – Windows	3.02.3 (A)
—	Ultra 3 Single Channel HBA BIOS (Controller Firmware) – Windows	3.02.3 (A)

Platform	Description	Version
—	ROM Flash Component - AC036322C2 drives – Linux	3A12 (F)
—	ROM Flash Component - AD018322BC drives – Linux	3A12(E)
—	ROM Flash Component - AD009322B9 drives – Linux	3A12(E)
—	ROM Flash Component - BD018122C0 and BD018222C1 drives – Linux	3B12(F)
—	ROM Flash Component - BD009122BA and BD009222BB drives – Linux	3B12(F)
—	ROM Flash Component - BF01864663 drives – Linux	3B0B(G)
—	ROM Flash Component - BD004153C3 and BD004253C4 drives – Linux	B417(F)
—	ROM Flash Component - AD00435332 drives – Linux	A417(E)
—	ROM Flash Component - BD00965333 and BD00975334 drives – Linux	B917(F)
—	ROM Flash Component - AD00935335 drives – Linux	A917(F)
—	ROM Flash Component - BF01865222 and BF03665223 drives – Linux	B014(H)
—	ROM Flash Component - BD0186459A, BD018745A3, BD0366459B, BD036745A4, and BD0726459C drives – Linux	B016(G)
—	ROM Flash Component - AD018345A6 drives – Linux	A016(E)
—	ROM Flash Component - AD00932372, AD01832375, and AC03632378 drives – Linux	ACJG (E)
—	ROM Flash Component - BD00962373, BD00972374, BD01862376, BD01872377, and BC0367237A drives – Linux	BCJG(E)
—	ROM Flash Component – BD00912578 and BD01812579 drives – Linux	BCJG(E)
—	ROM Flash Component - AD00933626 and AD01833627 drives – Linux	ADCB(E)
—	ROM Flash Component - BD009635CB, BD00973623, BD018635CC, BD01873624, BD03663622, BD03673625, and BC072638A2 drives – Linux	BDCB(E)
—	ROM Flash component - AD01836222, AD00935CCC, and AD00435CCB drives – Linux	HPA6(D)
—	ROM Flash component - BD01865CC4, BD01875CC7, BD00965CC3, BD00975CC6, BD00415CBC, and BD00425CC2 drives – Linux	HPB6(E)
—	ROM Flash Component - BD00962A66, BD00972A69, BD01862A67, and BD01872A6A drives – Linux	B008 (E)
—	ROM Flash Component - BD0096349A, BD009734A3, BD0186349B, and BD018734A4 drives – Linux	3B15 (E)
—	ROM Flash Component - BB009135B4, BB009235B6, BB018135B5, and BB018235B7 drives – Linux	B022(D)

Platform	Description	Version
—	ROM Flash Component - BD009635C3, BD009735C6, BD018635C4, BD018735C7, BD036635C5, and BD036735C8 drives – Linux	B022 (D)
—	ROM Flash Component - BD01864544, BD03664545, and BD07264546 drives – Linux	B20D (E)
—	ROM Flash Component - BD036659CC drive – Linux	3B01 (C)
—	ROM Flash Component - BD07265A22 drive – Linux	3B01 (C)
—	ROM Flash component - DGHS09U, DGHS09Y, and DGHS18Y drives - Linux	03F1 (C)
—	ROM Flash component - ST19171N, ST19171W, and ST19171WC drives – Linux	9A10 (C)
BL25p/BL45p	Online ROM Flash Component for Windows - HP ProLiant BL25p/BL45p (A02) Server Blades	2007.02.14
BL25p/BL45p	Online ROM Flash Component for Linux - HP ProLiant BL25p/BL45p (A02) Server Blades	2007.02.14
BL25p/BL45p	Systems ROMPaq Firmware Upgrade for HP ProLiant BL25p/BL45p (A02) Server Blades	2007.02.14(A)
BL30p	Online ROM Flash Component for Windows - HP ProLiant BL30p (I10) Server Blades	2005.10.27 (B)
BL30p	Online ROM Flash Component for Linux - HP ProLiant BL30p (I10) Server Blades	2005.10.27
BL30p	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL30p (I10) Server Blades	4.06(I10-10/27/2005)
BL40p	Online ROM Flash Component for Windows - HP ProLiant BL40p (I02) Server Blades	2004.09.15
BL40p	Online ROM Flash Component for Linux - HP ProLiant BL40p (I02) Server Blades	2004.09.15
BL40p	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL40p (I02) Server Blades	4.07 (I102-9/15/2004)
DL360 G4	Online ROM Flash Component for Windows - HP ProLiant DL360 G4 (P52) Servers	2007.07.16
DL360 G4	Online ROM Flash Component for Linux - HP ProLiant DL360 G4 (P52) Servers	2007.07.16
DL360 G4	Systems ROMPaq Firmware Upgrade for HP ProLiant DL360 G4 (P52) Servers	2007.07.16(A)
DL360 G4p	Online ROM Flash Component for Windows - HP ProLiant DL360 G4p (P54) Servers	2007.07.16
DL360 G4p	Online ROM Flash Component for Linux - HP ProLiant DL360 G4p (P54) Servers	2007.07.16
DL360 G4p	Systems ROMPaq Firmware Upgrade for HP ProLiant DL360 G4p (P54) Servers	2007.07.16 (A)
DL380 G4	Online ROM Flash component for Windows - HP ProLiant DL380 G4 (P51) Servers	2007.07.19
DL380 G4	Online ROM Flash Component for Linux - HP ProLiant DL380 G4 (P51) Servers	2007.07.19

Platform	Description	Version
DL380 G4	Systems ROMPaq Firmware Upgrade for HP ProLiant DL380 G4 (P51) Servers	2007.07.19 (A)
DL385	Online ROM Flash Component for Windows - HP ProLiant DL385 (A05) Servers	2006.03.01
DL385	Online ROM Flash Component for Linux - HP ProLiant DL385 (A05) Servers	2006.03.01
ML310 G2	Online ROM Flash Component for Windows - HP ProLiant ML310 G2 (W01) Servers	2006.01.20
ML310 G2	Online ROM Flash Component for Linux - HP ProLiant ML310 G2 (W01) Servers	2006.01.20
ML310 G2	ROMPaq Firmware Upgrade Diskette for HP ProLiant ML310 G2 (W01) Servers	2006.01.20 (A)
ML310 G3	Online ROM Flash Component for Windows - HP ProLiant ML310 G3 (W02) Servers	2007.08.03
ML310 G3	Online ROM Flash Component for Linux - HP ProLiant ML310 G3 (W02) Servers	2007.08.03
ML310 G3	Systems ROMPaq Firmware Upgrade for HP ProLiant ML310 G3 (W02) Servers	2007.08.03 (A)
ML370 G4	Online ROM Flash Component for Windows - HP ProLiant ML370 G4 (P50) Servers	2007.07.19
ML370 G4	Online ROM Flash Component for Linux - HP ProLiant ML370 G4 (P50) Servers	2007.07.19
ML370 G4	Systems ROMPaq Firmware Upgrade for HP ProLiant ML370 G4 (P50) Servers	2007.07.19 (A)
ML570 G3	Online ROM Flash Component for Windows - HP ProLiant ML570 G3 (P37) Servers	2007.10.23
ML570 G3	Online ROM Flash Component for Linux - HP ProLiant ML570 G3 (P37) Servers	2007.10.23
ML570 G3	Systems ROMPaq Firmware Upgrade for HP ProLiant ML570 G3 (P37) Servers	2007.10.23 (A)

- Firmware version 7.91 was the last release that contains the following Server ROM Flash components. They will continue to be available for download at the HP website (<http://www.hp.com>).

Platform	Description	Version
BIOS - System ROM	—	—
BL20p	Online ROM Flash Component for Linux - HP ProLiant BL20p (I01) Server Blades	2004.05.01
BL20p	Online ROM Flash Component for Windows - HP ProLiant BL20p (I01) Server Blades	2004.05.01
BL20p	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL20p (I01) Server Blades	2004.05.01
BL20p G2	Online ROM Flash Component for Linux - HP ProLiant BL20p G2 (I04) Server Blades	2004.09.16

Platform	Description	Version
BL20p G2	Online ROM Flash Component for NetWare - HP ProLiant BL20p G2 (I04) Server Blades	2004.09.16
BL20p G2	Online ROM Flash Component for Windows - HP ProLiant BL20p G2 (I04) Server Blades	2004.09.16
BL20p G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL20p G2 (I04) Server Blades	2004.09.16 4.09A
BL30p	Online ROM Flash Component for Linux - HP ProLiant BL30p (I10) Server Blades	2005.10.27
BL30p	Online ROM Flash Component for Windows - HP ProLiant BL30p (I10) Server Blades	2005.10.27 (B)
BL30p	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL30p (I10) Server Blades	2005.10.27 4.06A
BL40p	Online ROM Flash Component for Linux - HP BL40p (I02) Server Blades	2004.09.15
BL40p	Online ROM Flash Component for Windows - HP BL40p (I02) Server Blades	2004.09.15
BL40p	System ROMPaq Firmware Upgrade Diskette for HP ProLiant BL40p (I02) Server Blades	2004.09.15 4.07A
DL320 G2	Online ROM Flash Component for Linux - HP ProLiant DL320 G2 (D13) Servers	2004.09.15
DL320 G2	Online ROM Flash Component for Windows - HP ProLiant DL320 G2 (D13) Servers	2004.09.15
DL320 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL320 G2 (D13) Servers	2004.09.15 4.10A
DL320 G3	Online ROM Flash Component for Linux - HP ProLiant DL320 G3 (D18) Servers	2005.08.16
DL320 G3	Online ROM Flash Component for Windows - HP ProLiant DL320 G3 (D18) Servers	2005.08.16
DL320 G3	Systems ROMPaq Firmware Upgrade Diskette for ProLiant DL320 G3 (D18) Servers	2005.08.16 4.03A
DL360 G3	Online ROM Flash Component for Linux - HP ProLiant DL360 G3 (P31) Servers	2005.03.03
DL360 G3	Online ROM Flash Component for Netware - HP ProLiant DL360 G3 (P31) Servers	2005.03.03
DL360 G3	Online ROM Flash Component for Windows - HP ProLiant DL360 G3 (P31) Servers	2005.03.03
DL360 G3	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL360 G3 (P31) Servers	2005.03.03 4.12A
DL380 G3	Online ROM Flash Component for Linux - HP ProLiant DL380 G3 (P29) Servers	2004.09.15
DL380 G3	Online ROM Flash Component for Netware - HP ProLiant DL380 G3 (P29) Servers	2004.09.15
DL380 G3	Online ROM Flash Component for Windows - HP ProLiant DL380 G3 (P29) Servers	2004.09.15

Platform	Description	Version
DL380 G3	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL380 G3 (P29) Servers	2004.09.15 4.09A
DL560	Online ROM Flash Component for Linux - HP ProLiant DL560 (P30) Servers	2004.09.15
DL560	Online ROM Flash Component for NetWare - HP ProLiant DL560 (P30) Servers	2004.05.01
DL560	Online ROM Flash Component for Windows - HP ProLiant DL560 (P30) Servers	2004.09.15
DL560	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL560 (P30) Servers	2004.09.15 4.06A
DL580 G2	Online ROM Flash Component for Linux - HP ProLiant DL580 G2 (P27) Servers	2004.09.15
DL580 G2	Online ROM Flash Component for Windows - HP ProLiant DL580 G2 (P27) Servers	2004.09.15
DL580 G2	Online ROM Flash for NetWare - HP ProLiant DL580 G2 (P27) Servers	2004.09.15
DL580 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL580 G2 (P27) Servers	2004.09.15 4.12A
DL740	Online ROM Flash Component for Linux - HP ProLiant DL740 (P47) Servers	2004.09.15
DL740	Online ROM Flash Component for Linux - HP ProLiant DL740 (P47) Servers	2004.09.15 4.08A
DL740	Online ROM Flash Component for Windows - HP ProLiant DL740 (P47) Servers	2004.09.15
DL760	Online ROM Flash Component for Windows - HP ProLiant DL760 (P46) Servers	2003.05.05
DL760	Systems ROMPaq Firmware Upgrade for HP ProLiant DL760 (P46) Servers	2003.05.05 4.04A
DL760 G2	Online ROM Flash Component for Linux - HP ProLiant DL760 G2 (P44) Servers	2004.09.15
DL760 G2	Online ROM Flash Component for Windows - HP ProLiant DL760 G2 (P44) Servers	2004.09.15
DL760 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL760 G2 (P44) Servers	2004.09.15 4.08A
ML310	Online ROM Flash Component for Linux - HP ProLiant ML310 (D12) Servers	2004.09.15
ML310	Online ROM Flash Component for Windows - HP ProLiant ML310 (D12) Servers	2004.09.15
ML310	Online ROM flash for NetWare - HP ProLiant ML310 (D12) Servers	2004.05.01
ML310	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML310 (D12) Servers	2004.09.15 4.11A
ML330 G3	Online ROM Flash Component for Linux - HP ProLiant ML330 G3 (D15) Servers	2005.09.01

Platform	Description	Version
ML330 G3	Online ROM Flash Component for Netware - HP ProLiant ML330 G3 (D15) Servers	2004.05.01
ML330 G3	Online ROM Flash Component for Windows - HP ProLiant ML330 G3 (D15) Servers	2005.09.01
ML330 G3	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML330 G3 (D15) Servers	2005.09.01 4.09A
ML350 G3	Online ROM Flash Component for Linux - HP ProLiant ML350 G3 (D14) Servers	2004.09.15
ML350 G3	Online ROM Flash Component for Windows - HP ProLiant ML350 G3 (D14) Servers	2004.09.15
ML350 G3	Online ROM Flash for NetWare - HP ProLiant ML350 G3 (D14) Servers	2004.09.15
ML350 G3	Systems ROMPaq Firmware Upgrade Diskette for ProLiant ML350 G3 (D14) Servers	2004.09.15 4.10A
ML370 G3	Online ROM Flash Component for Linux - HP ProLiant ML370 G3 (P28) Servers	2004.09.15
ML370 G3	Online ROM Flash Component for Netware - HP ProLiant ML370 G3 (P28) Servers	2004.09.15
ML370 G3	Online ROM Flash Component for Windows - HP ProLiant ML370 G3 (P28) Servers	2004.09.15
ML370 G3	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML370 G3 (P28) Servers	2004.09.15 4.12A
ML530 G2	Online ROM Flash Component for Linux - HP ProLiant ML530 G2 (P22) Servers	2004.09.15
ML530 G2	Online ROM Flash Component for Windows - HP ProLiant ML530 G2 (P22) Servers	2004.09.15
ML530 G2	Online ROM Flash for NetWare - HP ProLiant ML530 G2 (P22) Servers	2004.05.01
ML530 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML530 G2 (P22) Servers	2004.09.15 4.10A
ML570 G2	Online ROM Flash Component for Linux - HP ProLiant ML570 G2 (P32) Servers	2005.04.26
ML570 G2	Online ROM Flash Component for Netware - HP ProLiant ML570 G2 (P32) Servers	2005.04.26
ML570 G2	Online ROM Flash Component for Windows - HP ProLiant ML570 G2 (P32) Servers	2005.04.26
ML570 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML570 G2 (P32) Servers	2005.04.26 4.09A

- Firmware version 7.91 was the last release that contains the following NetWare ROM Flash components. They will continue to be available for download at the HP website (<http://www.hp.com>).

Platform	Description	Version
BIOS - System ROM	—	—

Platform	Description	Version
BL20p G3	Online ROM Flash Component for NetWare - HP ProLiant BL20p G3 (I08) Server Blades	2006.02.14
BL20p G4	Online ROM Flash Component for NetWare - HP ProLiant BL20p G4 (I13) Server Blades	2007.04.06
BL460c	Online ROM Flash Component for NetWare - HP ProLiant BL460c (I15) Server Blades	2007.05.01
DL360 G4	Online ROM Flash Component for NetWare - HP ProLiant DL360 G4 (P52) Servers	2006.02.14
DL360 G4p	Online ROM Flash Component for NetWare - HP ProLiant DL360 G4p (P54) Servers	2006.02.14
DL360 G5	Online ROM Flash Component for NetWare - HP ProLiant DL360 G5 (P58) Servers	2007.05.01
DL380 G4	Online ROM Flash Component for NetWare - HP ProLiant DL380 G4 (P51) Servers	2006.04.26
DL380 G5	Online ROM Flash Component for NetWare - HP ProLiant DL380 G5 (P56) Servers	2007.05.01
DL385	Online ROM Flash Component for NetWare - HP ProLiant DL385 (A05) Servers	2006.03.01
DL385 G2	Online ROM Flash Component for NetWare - HP ProLiant DL385 G2 (A09) Servers	2007.04.07
DL580 G3	Online ROM Flash Component for NetWare - HP ProLiant DL580 G3 (P38) Servers	2006.08.08
DL580 G4	Online ROM Flash Component for NetWare - HP ProLiant DL580 G4 (P59) Servers	2007.04.17
ML310 G2	Online ROM Flash Component for NetWare - HP ProLiant ML310 G2 (W01) Servers	2006.01.20
ML310 G3	Online ROM Flash Component for NetWare - HP ProLiant ML310 G3 (W02) Servers	2007.03.10
ML350 G4	Online ROM Flash Component for NetWare - HP ProLiant ML350 G4 (D17) Servers	2006.02.15
ML350 G4p	Online ROM Flash Component for NetWare - HP ProLiant ML350 G4p (D19) Servers	2006.02.15
ML350 G5	Online ROM Flash Component for Netware - HP ProLiant ML350 G5 (D21) Servers	2007.05.01
ML370 G4	Online ROM Flash Component for NetWare - HP ProLiant ML370 G4 (P50) Servers	2006.02.14
ML370 G5	Online ROM Flash Component for NetWare - HP ProLiant ML370 G5 (P57) Servers	2007.05.01
ML570 G3	Online ROM Flash Component for NetWare - HP ProLiant ML570 G3 (P37) Servers	2006.08.08
ML570 G4	Online ROM Flash Component for NetWare - HP ProLiant ML570 G4 (P60) Servers	2007.04.17

- Firmware version 7.91 was the last release that contains the following SoftPaqs. They will continue to be available for download at the HP website (<http://www.hp.com>).

Platform	Description	Version
BIOS - System ROM	—	—
BL20p G3	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant BL20p G3 (I08) Server Blades	2006.02.14
DL360 G4	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL360 G4 (P52) Servers	2006.02.14
DL360 G4p	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL360 G4p (P54) Servers	2006.02.14
DL380 G4	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL380 G4 (P51) Servers	2006.04.26
DL385	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant DL385 (A05) Servers	2006.03.01A
ML310 G2	Systems ROMPaq Firmware Upgrade Diskette for HP ML310 G2 (W01) Servers	2006.01.20A
ML350 G4	Systems ROMPaq Firmware Upgrade Diskette for ProLiant ML350 G4 (D17) Servers	2006.02.15
ML350 G4p	Systems ROMPaq Firmware Upgrade Diskette for ProLiant ML350 G4p (D19) Servers	2006.02.15
ML370 G4	Systems ROMPaq Firmware Upgrade Diskette for HP ProLiant ML370 G4 (P50) Servers	2006.02.14
Firmware - Lights-Out Management	—	—
iLO	Options ROMPaq Firmware Upgrade Diskette for HP Integrated Lights-Out Management Controller	1.89 (A)
Firmware - Storage Controller	—	—
HP 6-Port	Firmware and BIOS for HP SATA HBA with RAID	4.2-1-9304
—	Options ROMPaq for Array Controllers	3.10A

HP Smart Update Manager

HP Smart Update Manager is used to deploy firmware in offline and online modes on Microsoft® Windows® and Linux systems. For more information, see the HP ProLiant Firmware Maintenance CD User Guide, which can be found on the Firmware Maintenance CD at `\compaq\docs\HPProLiantFirmwareMaintenanceCDUserGuide.pdf`.

You must have Acrobat Reader to read this document. To obtain the latest version of Acrobat Reader, visit the Adobe website (<http://www.adobe.com>).

General topics

- HP Smart Update Manager is available in English and Japanese only.
- To run HP Smart Update Manager in Japanese under SUSE LINUX Enterprise Server 9, you must use the command `setenv LANG ja_JP` to set the language.
- When running HP Smart Update Manager on any Microsoft® Windows® operating systems, you must enable WMI before starting HP Smart Update Manager or else discovery fails.
- Beginning in HP Smart Update Manager version 3.2.0, which is on the Firmware Maintenance CD version 8.10, the persistent data (Hosts and Groups) stored location on the system where HP Smart Update Manager is executed has changed. Persistent data entered with earlier versions of HP Smart Update Manager is moved automatically to a new location the first time HP Smart Update Manager version 3.2.0 or later is run. After the persistent data has been moved, the data no longer exists for use with earlier versions of HP Smart Update Manager. This process only occurs once. If an earlier version of HP Smart Update Manager is run after the persistent data has been moved and new persistent data is entered, it is not moved to the new storage location when HP Smart Update Manager version 3.2.0 or later is run.
- HP Smart Update Manager only supports updating one firmware component at a time when using the Add Supplemental feature with firmware on diskettes in offline mode. If you have more than one firmware component (each on separate diskettes) that you want to update via the Add Supplemental feature, you must deploy them one at a time. Otherwise, an internal error message is reported.
- The NIC firmware components cannot be deployed using the Add Supplemental feature. To add new versions of the NIC firmware, you must put the Firmware Maintenance CD on a USB key and put the desired component in the `/compaq/swpackages` directory.
- If you are running HP Smart Update Manager under a supported Linux operating system, if the HP Smart Update Manager buttons and fonts are not displayed correctly, you may need to change their display settings and/or X11 configuration to get the user interface to display properly.
- With the integration of concurrent HP ProLiant Support Packs (PSPs) and HP ProLiant firmware components, legacy pass-through applications for the HP Remote Deployment Utility (RDU) have been added to HP Smart Update Manager. The legacy applications have the old RDU names (`setup.exe`, `setupc.exe` and `setupex.exe`) but actually map existing RDU command-line parameters to the new HP Smart Update Manager interface and map HP Smart Update Manager return codes to those generated by the legacy RDU applications. These legacy RDU interfaces are

provided for backwards compatibility with user scripts written to deploy or use RDU. Future features and enhancements will only be added to the HP Smart Update Manager interface.

- HP Smart Update Manager can only flash firmware on hard drives that are attached to Smart Array controllers and certain QLogic and Emulex HBAs.
- No reboot message is displayed when running HP Smart Update Manager on SUSE LINUX Enterprise Server 9. The user can specify a reboot message to display before a server is rebooted after a successful installation of firmware and/or software. However, when running HP Smart Update Manager on SUSE LINUX Enterprise Server 9, the reboot message is not displayed because there is no access to the console when using SUSE LINUX Enterprise Server 9. This issue is not unique to HP Smart Update Manager; it is an operating system limitation.

Command line

- When running HP Smart Update Manager from the command line, if a component that you want to deploy is not needed on the system, the component installation is not attempted.
- When using HP Smart Update Manager to deploy firmware to remote targets via the command-line, if you do not issue the `/s` or `/silent` option (`-s` or `--silent` for Linux), the HP Smart Update Manager GUI is loaded. The GUI uses the provided data to bypass as much of the installation interview process as possible.
- When running HPSUM with the `/silent` option, there is no indication that any components have failed dependencies. If you run HPSUM with the `/silent` option and nothing appears to have changed, run HPSUM without the `/silent` option, and then check the Select Items to be Installed screen to see if any of the components have failed dependencies.

HP Smart Update Manager and component-related topics

- Even though a hard drive firmware component is supported by the Firmware Maintenance CD, not all firmware components support updating hard drives in all enclosures. HP Smart Update Manager might allow a user to select hard drive firmware for installation even though the hard drive is not supported in the enclosure. Firmware installation is attempted and fails because the hard drive is not in a supported enclosure. The component log does not include a reason why the failure occurred.
- The NIC firmware components do not support the IPv6 protocol. Therefore, when using the IPv6 protocol on the network and trying to deploy the NIC firmware using HP Smart Update Manager, HP Smart Update Manager appears to hang.
- Before updating the firmware on a Modular Smart Array 60 or Modular Smart Array 70 from version 1.42 or earlier to version 2.16 or later, read the advisory on the HP website (http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?lang=en&cc=us&objectID=c01361896&jumpid=reg_R1002_USEN).
- The HP NC-Series Broadcom Online Firmware Upgrade Utility for Linux components on the Firmware Maintenance CD v7.90 and later require a `tg3` driver version greater than or equal to 3.58b and `bnx2` driver versions greater than or equal to 1.4.41. If the `tg3` driver version is earlier than 3.58b or the `bnx2` driver version is earlier than 1.4.41, the installation of these components appears to be successful. However, the installation is not successful, and the user is not informed of the installation failure.

- HP Smart Update Manager only updates the NIC firmware that is programmed currently in the NIC. For example, if a PXE image is programmed currently and an iSCSI image is needed, then refer to the NIC firmware update tool, which can be found at the appropriate download page for your system configuration on the HP website (<http://www.hp.com/go/support>).
- When flashing NIC firmware to remote target servers, the NIC driver on the target server NIC being flashed will unload and reload as part of the flash operation. This action might cause a drop in connection to the remote server of up to 30 seconds.

HP Firmware CD Browser Utility

The HP ProLiant Firmware CD Browser Utility allows you to locate, save, install, and learn more about the components on the HP ProLiant Firmware Maintenance CD in online mode only. These components include online and offline firmware for servers, Smart Array controllers, NICs, lights-out management, blade infrastructure, tape options, QLogic and Emulex HBAs, and hard drives (SCSI - offline only and select SAS and SATA - offline and online).

The HP Firmware CD Browser Utility is available in English only.

HP Firmware CD Browser Utility Issues

- References to ROM Update Utility and Remote Deployment Utility should be replaced with HP Smart Update Manager.

Description of error

Many of the components on the Firmware Maintenance CD have references to the ROM Update Utility or the Remote Deployment Utility in their Description or Installation Notes.

Workaround

Whenever you see references to ROM Update Utility or the Remote Deployment Utility, substitute the HP Smart Update Manager. You can access HP Smart Update Manager by selecting the Install Firmware link on the Firmware Update tab in the Firmware CD user interface.

- There are inactive or incorrect links on some product pages.

Description of error

Some of the links are inactive or might take the user to an incorrect location on the following product pages when viewed using the HP Firmware CD Browser Utility:

- Online ROM Flash Component for Linux - HP ProLiant BL20p G4 (I13) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL25p G2 (A11) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL45p G2 (A12) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL460c (I15) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL465c (A13) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL680c G5 (I17) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant BL685c (A08) Server Blades
- Online ROM Flash Component for Linux - HP ProLiant DL320 G5 (W04) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL360 G5 (P58) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL365 (A10) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL380 G5 (P56) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL385 G2 (A09) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL580 G4 (P59) Servers
- Online ROM Flash Component for Linux - HP ProLiant DL585 G2 (A07) Servers
- Online ROM Flash Component for Linux - HP ProLiant ML310 G4 (W03) Servers

- Online ROM Flash Component for Linux - HP ProLiant ML310 G5/DL320 G5p (W05) Servers
- Online ROM Flash Component for Linux - HP ProLiant ML350 G5 (D21) Servers
- Online ROM Flash Component for Linux - HP ProLiant ML570 G4 (P60) Servers

Customer Advisories

- FIRMWARE UPGRADE RECOMMENDED to Prevent SAS Hard Drives Attached to a SMART Array P800 Controller from Failing to Come Online When Hot-Added into a Server Drive Bay. See the HP website
(http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c01489253).
- FIRMWARE UPGRADE REQUIRED to Prevent Rare Potential for Data Read/Write Errors on a RAID 6 or RAID 1+0 Volume Configured on Certain HP Smart Array SATA/SAS Controllers After Multiple Drive Failures and One Hot-Replacement. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c01473263>).
- (Revised) Firmware Upgrade Components for SATA Hard Drives attached to an HP Smart Array P600 Controller running Firmware Version 1.88 or 1.98 are not currently supported under Linux. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c01403290>).
- HP NC-Series Network Adapter Firmware Components for Windows can not be deployed using HP Smart Update Manager version 3.1.0 on Firmware Maintenance CD version 8.0. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c01409706>).
- Minimum versions of System ROM Support for Quad-Core AMD-Based Processors on HP ProLiant Servers. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c01421363>).
- Firmware Upgrade Components for SAS/SATA Hard Drives attached to an HP Smart Array P600 Controller running firmware v1.88 or v1.98 are not currently supported under Linux. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c01403290>).
- Non-ROM Based Setup Utility (RBSU) Servers Cannot Boot to the Firmware Maintenance CD Version 7.50. See the HP website
(<http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?objectID=c00736436>).

Workaround

Go to the appropriate product page on the Software and Drivers download website (<http://www.hp.com/go/support>), and then follow the links.