

Reo,

I believe there are two main reasons. One is that Dynamic has auto login. The other is that Static uplinks were tied into specific downlink bays. Depending on the number of uplink and the servers installed, bandwidth could be an issue. If the site was using full height, BL870s or the new BL890 some uplinks may not be used.

Four uplinks 4:1 oversubscribe:



Two uplinks 8:1 oversubscribe:



One Uplink 16:1 oversubscribe:

