

## Uplink Port Information

Port	WWN	SAN Fabric	Port Speed Setting	Connector Status	Connected To
1	20:00:F4:CE:46:AE:0A:BE	P2000SAN	8 Gb	LOGGED-IN	10:00:00:05:33:B8:57:6F
2	20:11:F4:CE:46:AE:0A:BE	P2000SAN	8 Gb	LOGGED-IN	10:00:00:05:33:B8:57:6F
3	20:12:F4:CE:46:AE:0A:BE	P2000SAN	8 Gb	LOGGED-IN	10:00:00:05:33:B8:57:6F
4	20:13:F4:CE:46:AE:0A:BE	P2000SAN	8 Gb	LOGGED-IN	10:00:00:05:33:B8:57:6F

## Server Port Information

Less &lt;

HBA Port	Server Blade	SAN Fabric	Connected To	Profile	HBA Port Speed	HBA Port Status	HBA WWPN
1	Device Bay 1 (ProLiant BL460c G6)	P2000SAN		XenTest1	4 Gb	LOGGED-IN	50:06:0B:00:00:C2:62:00
2	Device Bay 2 (ProLiant BL460c G6)	P2000SAN		XenTest2	0 Gb	NOT-LOGGED-IN	50:06:0B:00:00:C2:62:04
3	Device Bay 3 (ProLiant BL460c G6)	P2000SAN		XenTest3	4 Gb	LOGGED-IN	50:06:0B:00:00:C2:62:08
4	Device Bay 4 (ProLiant BL460c G6)	P2000SAN		XenTest4	0 Gb	NOT-LOGGED-IN	50:06:0B:00:00:C2:62:0C
5					0 Gb	NOT-LOGGED-IN	
6					0 Gb	NOT-LOGGED-IN	
7	Device Bay 7 (ProLiant BL460c G6)	P2000SAN		OraDWTST	0 Gb	NOT-LOGGED-IN	50:06:0B:00:00:C2:62:10
8	Device Bay 8 (ProLiant BL460c G6)	P2000SAN		TurnNBurn	0 Gb	NOT-LOGGED-IN	50:06:0B:00:00:C2:62:14